

PHOTOGRAPHS
M.V. "LEON I"
Wire Rope Inspection
@ Chesapeake Engineering & Design, Inc.
Annapolis, Maryland
October 8, 2003
Our Case No. WT-21833



CAPTIONS TO PHOTOGRAPHS

M.V. "LEON I"
Wire Rope Inspection
@ Chesapeake Engineering & Design, Inc.
Annapolis, Maryland
October 8, 2003
Our Case No. WT-21833

- 1) As stored on pallets
- 2) As stored on pallets
- 3) As stored on pallets
- 4) Local wire break
- 5) Local wire break
- 6) Local wire break
- 7) Cut end of wire rope
- 8) Frayed end
- 9) Part of failed section
- 10) Part of failed section
- 11) Part of failed section
- 12) Part of failed section
- 13) Cut end (possible where test piece taken)
- 14) Typical tensile break
- 15) Typical tensile break
- 16) Intermediate section of wire rope
- 17) Broken strand
- 18) General condition of wire rope
- 19) General condition of wire rope
- 20) General condition of wire rope
- 21) General condition of wire rope
- 22) Cut ends (not failure)
- 23) Failed area of wire rope
- 24) Failed area of wire rope
- 25) Failed area of wire rope
- 26) Taking a sample strand in area of failure
- 27) Area of failure
- 28) Area of failure
- 29) Area of failure





























